



SELFPAY 1060











52,2 kg



VISTA DALL'ALTO
PER FORATURE
FISSAGGIO PIASTRA:
6 fori Ø6

TOP VIEW FOR
THE DRILLINGS OF
THE FIXING PLATE:
6 holes Ø6



A4 - 1:10 - millimiters


CASHMATIC

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF CASHMATIC ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF CASHMATIC IS PROHIBITED


SELFPAY 1060

STAND FISSO
FIXED STAND

25 kg




77,2 kg tot.




Il fissaggio tra SelfPay e stand avviene tramite le forature sul fondo macchina. La piastra antiribaltamento è da rimuovere.

The SelfPay is attached to the stand using the holes on the bottom of the machine. The anti-tip plate must be removed.



STAND ORGANIZER BASSO
LOW MOBILE STAND ORGANIZER

24 kg



76 kg tot.

LIMITAZIONE DI RESPONSABILITÀ

Cashmatic non autorizza la configurazione ibrida con Visualpay27, 32 e DoubleSide su stand con ruote per motivi di sicurezza (ribaltamento).
Tale configurazione, anche se tecnicamente fattibile, non è conforme agli standard di sicurezza per cui Cashmatic non approva e non si assume la responsabilità per tale combinazione.
Le uniche combinazioni ibride permesse con questo stand con ruote includono esclusivamente VP17/22 Desk.

LIMITATION OF LIABILITY

For safety reasons (risk of tipping over), Cashmatic does not authorize hybrid configurations involving Visualpay27, 32, or DoubleSide units mounted on stands equipped with wheels.
Although such a configuration may be technically feasible, it does not comply with safety standards; therefore, Cashmatic does not approve it and assumes no liability for such a combination.
The only hybrid configurations permitted for use with this wheeled stand are those involving the VP17/22 Desk model.

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF CASHMATIC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF CASHMATIC IS PROHIBITED